



Part Number: TY1544-20

Part Description: Hand Wind Assembly

## Specifications

Product Families:	Structures
Product Group:	Panels
Part Number	TY1544-20
Root Part Number	TY1544-20
ATA Chapter 2 Digit	78
ATA Chapter 4 Digit	78-32
ATA Chapter 6 Digit	78-32-41
MFR / Manufacture -CAGE Code	Goodrich
Application	V2500

## Repair

Part Number	TY1544-20
Description	Hand Wind Assembly
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Overhaul	Yes
Repair Facility	Hialeah

## Logistics

Part Number	TY1544-20
Description	Hand Wind Assembly

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

**630 Aerospace where quality is built in not inspected.**



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737