



Part Number: 113T3100-59SP

Part Description: Outboard Trailing Edge Flap Assembly

Specifications

Product Families:	Flight Controls and Surfaces
Product Group:	Flaps
Part Number	113T3100-59SP
Root Part Number	113T3100-59SP
ATA Chapter 2 Digit	57
ATA Chapter 4 Digit	57-53
ATA Chapter 6 Digit	57-53-51
MFR / Manufacture -CAGE Code	Boeing
Application	B757

Repair

Part Number	113T3100-59SP
Description	Outboard Trailing Edge Flap Assembly
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Overhaul	Yes
Repair Facility	Miami Lakes

Logistics

Part Number	113T3100-59SP
Description	Outboard Trailing Edge Flap Assembly

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

630 Aerospace where quality is built in not inspected.



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737