



Part Number: 113T3100-95SP

Part Description: Outboard Trailing Edge Flap Assembly

## Specifications

Product Families:	Flight Controls and Surfaces
Product Group:	Flaps
Part Number	113T3100-95SP
Root Part Number	113T3100-95SP
ATA Chapter 2 Digit	57
ATA Chapter 4 Digit	57-53
ATA Chapter 6 Digit	57-53-51
MFR / Manufacture -CAGE Code	Boeing
Application	B757

## Repair

Part Number	113T3100-95SP
Description	Outboard Trailing Edge Flap Assembly
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Overhaul	Yes
Repair Facility	Miami Lakes

## Logistics

Part Number	113T3100-95SP
Description	Outboard Trailing Edge Flap Assembly

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

**630 Aerospace where quality is built in not inspected.**



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737