



Part Number: 315A2500-10

Part Description: Thrust Reverser Sleeve Assembly

## **Specifications**

Product Families:	Harnesses
Product Group:	Engine Systems
Part Number	315A2500-10
Root Part Number	315A2500-XX
ATA Chapter 2 Digit	78
ATA Chapter 4 Digit	78-31
ATA Chapter 6 Digit	78-31-24
MFR / Manufacture -CAGE Code	Boeing
Application	CFM56

## Repair

Part Number	315A2500-10
Description	Thrust Reverser Sleeve Assembly
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Overhaul	Yes
Repair Facility	Miami Lakes

## Logistics

Part Number	315A2500-10
Description	Thrust Reverser Sleeve Assembly

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

630 Aerospace where quality is built in not inspected.



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737