



Part Number: 59T756

Part Description: Turbine case cooling air valve control cable

Specifications

Product Families:	Harnesses
Product Group:	Engine Systems
Part Number	59T756
Root Part Number	59T756
ATA Chapter 2 Digit	75
ATA Chapter 4 Digit	75-24
ATA Chapter 6 Digit	75-24-13
MFR / Manufacture -CAGE Code	Aero Controlex Group
Application	Unassigned

Repair

Part Number	59T756
Description	Turbine case cooling air valve control cable
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Repair Facility	Hialeah

Logistics

Part Number	59T756
Description	Turbine case cooling air valve control cable

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

630 Aerospace where quality is built in not inspected.



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737