

TY1542-50

Part Number: TY1542-50

Part Description: Lower Locking Actuator

Specifications

Product Families:	Accessories
Product Group:	Engine Systems Accesories
Part Number	TY1542-50
Root Part Number	TY1542-50
ATA Chapter 2 Digit	78
ATA Chapter 4 Digit	78-32
ATA Chapter 6 Digit	78-32-43
MFR / Manufacture -CAGE Code	Goodrich
Application	V2500

Repair

Part Number	TY1542-50
Description	Lower Locking Actuator
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Overhaul	Yes
Repair Facility	Hialeah

Logistics

Part Number	TY1542-50
Description	Lower Locking Actuator

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

630 Aerospace where quality is built in not inspected.

